



FIG. 1






FIG. 5

FIG. 6 is a schematic diagram of the system 30. The system 30 includes a motor 86, a mirror 64, a motor 76, a laser 70, a mirror 74, and a computer 78. The motor 86 is connected to the mirror 64. The mirror 64 is connected to the motor 76. The motor 76 is connected to the laser 70. The laser 70 is connected to the mirror 74. The mirror 74 is connected to the computer 78. The computer 78 is connected to the motor 86.




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG.10

30

FIG. 10




FIG.11




FIG.12

30




FIG. 13




FIG. 14




FIG. 15